









2

①	 M6X50	x20
②	 M6X70	x2
③	 M6	x22
④	 M6	x22
⑤	 M4X12	x6
⑥	 M4X16	x4
⑦	 M6X16	x6
⑧	 M6X20	x20


3

9	 M3X6	x2
10	 M5X12	x4
11	 2mm	x1
12	 3mm	x1
13	 5mm	x1


4




B




C



A




D



E





F



G




H



J


5



Allen wrench M6

Secure the screw but do
not lock it tightly.

6



Allen wrench M6
Secure the screw but do
not lock it tightly.


7

(8X) 1

(8X) 3


(8X) 4

13



Allen wrench M6

Secure the screw but do not lock it tightly.




8

(8X) ①


(8X) ③

(8X) ④

⑬



Allen wrench M6



Allen wrench M6




Tighten all 28 screws that were not fully tightened in the previous steps.

LP-C2 Industrial
Machine

9

(4X) ⑧
⑬

Allen wrench M6




⑪
⑫

The tailstock of
the LP-C2 machine
needs to be
removed here.


10

(2X) ⑨



⑪



Allen wrench M3




B




(6X) ⑤

⑫



Allen wrench M4


1 1



12

(4X) ⑥

⑫




Allen wrench M4

(4X) ⑦

⑬



Allen wrench M6



C

Note that part C should be installed centrally, with equal margins on both sides.